

# BODY LOC


COLLISION REPAIR EQUIPMENT



## BL-76RASP

### NEW BODY LOC

## RAPID ANCHORING SYSTEM PACKAGE



### Consists of:

- 1) BL-76RAS Rapid Anchoring Clamp (4)
- 2) BL-60T Tall D-Lux Roller Plates
- 2) BL-50T Tall Plain Roller Plates
- 4) BL-71 2-1/2" System Tydown (installation not included)
- 1) BL--75E Socket for Anchoring System

Body Loc, Inc. 5738 Newt Patterson Road, Mansfield, TX 76063  
Toll: 800-510-8564 • Office: 817-478-9570 • Fax: 817-478-8360  
[www.bodyloc.com](http://www.bodyloc.com) • [info@bodyloc.com](mailto:info@bodyloc.com)